## STANLEY TOOLS PRICE LIST

Applying to Catalog No. 60

Effective

August 26, 1957

## STANLEY TOOLS

DIVISION OF THE STANLEY WORKS NEW BRITAIN, CONNECTICUT, U. S. A.



STANLEY THE TOOL BOX OF THE WORLD

No.	Item	Each	Page	No.	Item	Each	Page
0	18" Level, Wood	\$4.30	17	10A	3" Ratchet Screw Driver	2.20	27
	24" Level, Wood	4.40	17		4" Ratchet Screw Driver	2.30	27
_ 1	28" Level, Wood	4.70	17		<ul><li>5" Ratchet Screw Driver</li><li>6" Ratchet Screw Driver</li></ul>	2.50	27 27
0	2½" x 5" Scraper, Hand 3 " x 5" Scraper, Hand	1.20 1.30	$\begin{array}{c} 24 \\ 24 \end{array}$		8" Ratchet Screw Driver	2.60 2.80	27
	3 " x 6" Scraper, Hand	1.40	24	B10	10' Rule Blade	.80	22
1	1/16" Drill Points	.20	11	B10W	10' Rule Blade	.80	22
î	6" Square, Try and Mitre	2.30	32	10 34	%" Punch, Center	.40	21
	8" Square, Try and Mitre	2.60	32	11	20 oz. Hammer, Nail	4.75	12
	10" Square, Try and Mitre	<b>2.90</b>	32	1136	16 oz. Hammer, Nail	4.50	12
ST1	20 oz. Hammer, Nail	5.25	12	OH11	20 oz. Hammer, Nail	4.75	12
ST1A	20 oz. Hammer, Nail	5.25	12	OH1136	16 oz. Hammer, Nail	4.50	12
ST1 ½ ST1 ½ A	16 oz. Hammer, Nail	4.99 4.99	$\frac{12}{12}$	1134	1/32" Nail Set	.40 .40	19 19
2	5/64" Drill Points	.20	11		5/64" Nail Set	.40	19
2B	¼" Chisel, Cold	.95	10		3/32" Nail Set	.40	19
20	18" Chisel, Cold	.95	10		4/32" Nail Set	.40	19
	% " Chisel, Cold	1.15	10		5/32" Nail Set	.40	19
	½" Chisel, Cold	1.35	10	12	13 oz. Hammer, Nail	4.50	12
	% " Chisel, Cold	1.95	10	12	6" Square, Try	2.00	32 32
СТО	%4" Chisel, Cold	2.40	10 12	200	8" Square, Try	2.30 2.90	32
ST2	13 oz. Hammer, Nail	4.99			12" Square, Try	3.35	32
3	3/32" Drill Points	.20	11	12B	½" Chisel, Plbrs	1.60	10
3	8 " Plane, Bench	10.50	19	B12W	12' Rule Blade	1.00	22
3B	¼" Chisel, Cold	.95 .95	$\begin{array}{c} 10 \\ 10 \end{array}$	OH12	13 oz. Hammer, Nail	4.50	12
	% " Chisel, Cold	1.15	10	13B	%" Chisel, Plbrs	1.90	10
	½" Chisel, Cold	1.35	10	14	2' Square, Steel	3.95	32
	% " Chisel, Cold	1.95	10	14	Trammel Point, Pair	2.50	33
	¾ " Chisel, Cold	2.40	10	14B	¾ " Chisel, Plbrs	2.15	10
4	7/64" Drill Points	.20	11	14B	2' Square, Steel	4.30	32
4	9 " Plane, Bench	10.70	19	14HS	Countersink	1.50	10
4	Trammel Point, Pair	2.50	33	15A	2" Ratchet Screw Driver	2.00	27
4B	14" Chisel, Cold	.95	10		3" Ratchet Screw Driver	2.10	27
	%" Chisel, Cold	1.15 1.35	10 10		4" Ratchet Screw Driver	2.10	27
4 1/2	10 " Plane, Bench	12.90	19	3 - 3 - 13	5" Ratchet Screw Driver 6" Ratchet Screw Driver	2.20 2.20	$\begin{array}{c} 27 \\ 27 \end{array}$
5	1/8 " Drill Points	.20	11		8" Ratchet Screw Driver	2.30	$\overline{27}$
5	14 " Plane, Bench	11.50	19	15B	5/32" Punch, Long	.65	21
5B	1/16" Punch, Hand	.55	20	16B	6/32" Punch, Long	.80	21
35	1/8 " Punch, Hand	.60	$\tilde{20}$	17	Awl, Brad	.90	5
	3/16" Punch, Hand	.80	20	RD171/2	Set, Auger Bit	16.50	6
	1/4 " Punch, Hand	.90	20	18	6" Bevel	2.75	5
	5/16" Punch, Hand	1.25 1.50	$\begin{array}{c} 20 \\ 20 \end{array}$		8" Bevel	2.95	5
E 1/	11½" Plane, Bench	11.20	19	400	10" Bevel	3.15	5
51/4		.95	5	18B	8/32" Punch, Long	2.00	21
6	Awl, Scratch			20	2½" Screw Driver	1.00	24
6	9/64" Drill Points	.20	11	JAC 402 76	3 "Screw Driver	1.00 1.00	$\begin{array}{c} 24 \\ 24 \end{array}$
6	18 " Plane, Bench	17.80	19		5 " Screw Driver	1.10	24
6B	4/32" Punch, Machine	.60	20	PLOOD 11111	6 " Screw Driver	1.20	24
	5/32" Punch, Machine 6/32" Punch, Machine	.6 <b>0</b> .6 <b>5</b>	$\begin{array}{c} 20 \\ 20 \end{array}$		8 " Screw Driver	1.50	24
	8/32" Punch, Machine	.75	20		10 " Screw Driver	1.75	$\begin{array}{c} 24 \\ 24 \end{array}$
	10/32" Punch, Machine	.90	20	20	TANKS MAIL	2.05	32
6W	6' Rule Blade	.55	22	20	6" Square, Try	2.65 2.90	32
7	Awl, Scratch	1.05	5		10" Square, Try	3.30	32
7	5/32" Drill Points	.20	11		12" Square, Try	4.00	32
7	22 " Plane, Bench	22.00	19	21	20 oz. Hammer, Nail	4.75	12
	11/64" Drill Points	.20	11	21	1½" Screw Driver	.80	24
8	_			21	12" Square, Combination	3.50	31
8	24 " Plane, Bench	25.35	19	21 1/2	16 oz. Hammer, Nail	4.50	12
8	8¼" Tool Holder	1.00	28	OH21	20 oz. Hammer, Nail	4.75	12
8B	%" Punch, Center	.55	21	OH21 1/2	16 oz. Hammer, Nail	4.50	12
3	8' Rule Blade	.70	22	22	3" Dowel, Sharp	1.15	11
8W	8' Rule Blade	.70	22	22	12" Square, Combination	3.85	31
9	Drill Point Set	1.68	11	24	24" Bar, Ripping	2.20	. 5
9B	%" Punch, Prick	.55	21	25	6" Bevel	2.00	5
91/4	6 "Plane, Block	4.50	19		8" Bevel	2.10	5
	6 " Plane, Block	5.95	19		10" Bevel	2.35	5

No.	Item	Each	Page	No.	Item	Each	Page
25	2½" Screw Driver	.90	24	52	13 oz. Hammer, Nail	4.00	12
861 861	3 " Screw Driver	.90	24	52	3½" Screw Driver	1.70	25
	4 "Screw Driver	.90		52 1/2	10 oz. Hammer, Nail	3.95	12
	5 "Screw Driver	1.00	24	53	7 oz. Hammer, Nail	3.95	12
	6 "Screw Driver	1.10	~ .	55	2 " Chisel, Wood	4.50	
	8 " Screw Driver	1.50 1.75	24	57	6" Wing Divider	3.50	
				100 111	8" Wing Divider	3.75	
26	16" Screw Driver Bit	.70 .70	29	58	6" Wing Divider	4.00	35
	"Screw Driver Bit	.70		43 144	8" Wing Divider	4.25	
	%" Screw Driver Bit	.80		59	Dowel, Jig	7.00 2.60	
	½" Screw Driver Bit	.80	29	60	4" Chisel, Wood	2.60	
30	Angle Divider	5.60	5	1.00	½" Chisel, Wood	2.70	-
30	30" Bar, Ripping	2.55	5	7 08 1	% " Chisel, Wood	2.80	9
30A	Sp. Ratchet Screw Driver	8.50	27	12. 93.1	% " Chisel, Wood	2.80	^
31A	Sp. Ratchet Screw Driver	11.00	27	1	1 " Chisel, Wood	3.15	-
BX-D32 1/2	Set, Auger Bit	33.50	6		1¼" Chisel, Wood	3.50	_
RD32 1/2	Set, Auger Bit	29.50	6	1 7 77 6	1½" Chisel, Wood	4.00 4.70	
H33	Nail Claw	1.59	19	00	2 "Chisel, Wood	43.00	200
34V	4" Level, Metal	7.00	18	60	Mitre Box	4.35	
0.,	6" Level, Metal	7.30		60B		5.95	
	8" Level, Metal	8.30		60 1/2	6 " Plane, Block	3.00	
	10" Level, Metal	10.40	18	65	7 " Plane, Block	7.50	
34V	2' Rule, Bench	2.20		65	13" Scraper, Box	3.30	
34 1/4 V	1' Rule, Bench	1.90		70 C70	Scraper Iron	.50	~ .
36	36" Bar, Ripping	2.75	5	71	Bit. Expansive	5.75	
36	6" Level, Metal	7.65		71	7½" Plane, Router	10.70	
	9" Level, Metal	8.15		71B	Bit, Expansive	6.85	
	12" Level, Metal	8.65		72	Cutter	1.40	-
	18" Level, Metal	10.10 11.35		73	Cutter	1.20	_
36G	6" Level, Metal	8.25		74	Adjusting Screw	.40	7
300	9" Level, Metal	8.45		74	1/4" Chisel, Cold	.60	
	12" Level, Metal	8.95	18		16" Chisel, Cold	.60	
	18" Level, Metal	10.40	40		% " Chisel, Cold	.65	
	24" Level, Metal	11.65	~ 4		½" Chisel, Cold	.80 .90	
36 16 L	Rule, Caliper	2.60			%" Chisel, Cold	1.15	100
36 1/2 R	Rule, Caliper	2.60			%" Chisel, Cold	1.55	
37G	12" Level, Metal	12.15			1 " Chisel, Cold	1.90	
	18" Level, Metal	13.40	10		½" x 12" Chisel, Cold	1.10	
381/2	24" Level, Metal	15.45 2.20			%" x 12" Chisel, Cold	1.35	
39 16	6" Level, Metal	2.70			%4" x 12" Chisel, Cold	1.55	
40	%" Chisel, Wood	2.90	_	in the literal	%4" x 18" Chisel, Cold %a" x 12" Chisel, Cold	1.95 2.05	
40	1/4" Chisel, Wood	3.00		8 41.3	1 " x 12" Chisel, Cold	2.40	
	%" Chisel, Wood	3.00		81.1	1 " x 18" Chisel, Cold	3.30	40
	½" Chisel, Wood	3.20	_	75	Clamp. Screw	.35	
	%" Chisel, Wood	3.30	-	75	4 " Plane, Rabbet	2.40	
	%4" Chisel, Wood	3.40		76	Washer	.40	-
	1 Offisci, Wood	3.70 4.35		77	Cutter	1.50	
	14" Chisel, Wood	4.65	_	78	81/4" Plane, Rabbet	7.80	
	2 " Chisel, Wood	5.45		078	Soldering Iron Tip	3.60	
41	Drill, Push	6.75		80	Scraper	3.60	
42	Saw Set	5.25			Scraper	3.85	24
43	Saw Set	10.10			Scraper Iron	.60	
45	Drill, Push	5.75		81	Tool Holder Bit	.45	
45	1½" Screw Driver	.85	_ ~-	82	Tool Holder Bit	.45	
45	2½" Screw Driver	.85		83	Tool Holder Bit	.45	
	3 " Screw Driver	.85		84	Tool Holder Bit	.45 .45	
	4 " Screw Driver	.85				1.85	
	5 " Screw Driver	.90			Gauge, Marking	10.60	
	6 " Screw Driver	.90			4 " Plane, Rabbet	.90	
	8 " Screw Driver	1.15		90	2 " Screw Driver	.90	~-
47	Bit Gauge	1.00			3 " Screw Driver	1.00	
B48W	8' Rule Blade	.75	_		4 " Screw Driver	1.10	~~
49	Bit Gauge	1.40			5 " Screw Driver	1.20	
50	Mitre Box	29.95			6 "Screw Driver	1.20	
51	20 oz. Hammer, Nail	4.25			8 "Screw Driver	1.60	~~
51	1%" Screw Driver	1.40			10 " Screw Driver	2.00	
51A	20 oz. Hammer, Nail	4.25			12 " Screw Driver	2.30 3.00	~ ~ ~
51 36	16 oz. Hammer, Nail	4.00				3.50	
51 1/2 A	16 oz. Hammer, Nail	3.95	, 14		TO NOTO!! DITTOIT!!!!!!!	2.20	

No.	Item	Each	Page	No.	Item	Each	Pag
92	5½" Plane, Rabbet	12.40	20	110	7 " Plane, Block	3.25	20
93	6 1/2" Plane, Rabbet	14.20	20	112	12" Bar, Ripping	1.35	5
95	1 1/2" Screw Driver	.85	25	116	6' Rule, Zig-Zag	2.10	23
	2½" Screw Driver	.85	25	118	18" Bar, Ripping	1.90	5
	3½" Screw Driver	.90	25	118	6 " Plane, Block	6.30	
	4 ½" Screw Driver	1.00	25 25	121	Soldering Iron Tip	2.00	
	5½" Screw Driver	1.05 1.15	25	122	Soldering Iron Tip	2.30	
	8½" Screw Driver	1.35	25	122	9" Square, Combination	3.25	
	10½" Screw Driver	1.45	25	122	12" Square, Combination	3.25	
98	Gauge, Marking	4.35	12	123	Soldering Iron Tip	4.10	
100	3/16" Bit, Auger	1.70	5	100		2.45	
100	4/16" Bit, Auger	1.60	5	124	24" Bar, Ripping	1.00	
	5/16" Bit, Auger	1.60	5	125	4/16" Bit, Electric Drill 5/16" Bit, Electric Drill	1.00	
	6/16" Bit, Auger	1.70	5	F. 04.8	6/16" Bit, Electric Drill	1.00	
	7/16" Bit, Auger	1.85 2.00	5 5	10 00.77	7/16" Bit, Electric Drill	1.10	
	8/16" Bit, Auger 9/16" Bit, Auger	2.10	5	9 00 22	8/16" Bit, Electric Drill	1.15	
	10/16" Bit, Auger	2.10	5	126	6' Rule, Zig-Zag	1.75	2
	11/16" Bit, Auger	2.20	5	127	Soldering Iron Tip	2.10	3
	12/16" Bit, Auger	2.30	5	128	Bit, Expansive	2.98	
	13/16" Bit, Auger	2.40	5 5	129	Bit, Expansive	3.59	
	14/16" Bit, Auger	2.70 2.80	5	130	30" Bar, Ripping	2.75	,
	15/16" Bit, Auger	2.90	5	130A	Sp. Ratchet Screw Driver	9.30	2
	17/16" Bit, Auger	3.35	5	131A	Sp. Ratchet Screw Driver	11.80	
	18/16" Bit, Auger	3.70	5	135A	Sp. Ratchet Screw Driver	8.20	
	20/16" Bit, Auger	3.95	5	136	36" Bar, Ripping	3.20	
	22/16" Bit, Auger	4.40	5	136	Rule, Caliper	1.69	
	24/16" Bit, Auger	5.15 6.25	5	1361/2	Rule, Caliper	1.98	
	28/16" Bit, Auger	7.20	5	137	½" Countersink	.60	
	32/16" Bit, Auger	8.10	5	139	¾ " Countersink	1.00	-
100	2' Square, Steel	4.80	32	147	Soldering Iron Tip	2.00	
100B	2' Square, Steel	5.20	32	147A	Soldering Iron Tip	2.10	_
R100	2' Square, Steel	6.25	32	148	Soldering Iron Tip	2.00	
100	2' Square, Steel	5.10	$\begin{array}{c} 32 \\ 32 \end{array}$	149	Gauge, Bevel	.20	_
100B	2' Square, Steel	5.50 6.40	$\frac{32}{32}$	149	Soldering Iron Tip	2.40	
100C R100	2' Square, Steel	9.20	32	150	Soldering Iron Tip	2.40	
100ED	4/16" Bit, Electric Drill	1.25	6	151	20 oz. Hammer, Nail	5.05	
LOOLD	5/16" Bit, Electric Drill	1.35	6	151	Soldering Iron Tip	2.60	_
	6/16" Bit, Electric Drill	1.50	6	151	10" Spoke Shave	2.50	
	7/16" Bit, Electric Drill	1.60	6	151A	20 oz. Hammer, Nail	5.05	-
	8/16" Bit, Electric Drill	1.70	$^6_6$	151M	10" Spoke Shave	2.80	
	9/16" Bit, Electric Drill 10/16" Bit, Electric Drill	1.95 2.15	6	H151	1 ""C" Clamp	.25	
	11/16" Bit, Electric Drill	2.35	6	151 1/2	16 oz. Hammer, Nail	4.80	
	12/16" Bit, Electric Drill	2.50	6	151 36 A	16 oz. Hammer, Nail	4.80	_
	13/16" Bit, Electric Drill	2.60	6	152	Soldering Iron Tip	3.30	
	14/16" Bit, Electric Drill	2.75	6	H152	2 ""C" Clamp	.39	
	15/16" Bit, Electric Drill	2.95	6	153	Soldering Iron Tip	3.30	
101	16/16" Bit, Electric Drill	3.15		155	Soldering Iron Tip	3.50	
101	20 oz. Hammer, Nail	3.75	13 20	H155	2 ½ " "C" Clamp	.72	_
101	3½" Plane, Block	1.19		156	Soldering Iron Tip	4.20	
101A	20 oz. Hammer, Nail	3.75 3.50	$\begin{array}{c} 13 \\ 13 \end{array}$	156F	6' Rule, Zig-Zag	1.75	2
101 ½ 101 ½ A	16 oz. Hammer, Nail	3.50	40	H156	3 " "C" Clamp	.59	
101 72 A 102	3/16" Bit, Dowel	1.70	6	157	Soldering Iron Tip	6.40	3
102	4/16" Bit, Dowel	1.70	6	H157	6 " "C" Clamp	.72	
	5/16" Bit, Dowel	1.70	6	158	Soldering Iron Tip	6.80	9
	6/16" Bit, Dowel	1.85	6	160B	32 oz. Hammer, Linesman's	5.15	1
	7/16" Bit, Dowel	2.00	6	162	Soldering Iron Tip	4.20	9
	8/16" Bit, Dowel	2.10	6	165	5 oz. Hammer, Bill Posters	3.10	1
	9/16" Bit, Dowel	2.20		166	7½ oz. Hammer, Bill Posters	3.20	
102	13 oz. Hammer, Nail	3.50	13	166	6' Rule, Zig-Zag	2.10	-
103	7 oz. Hammer, Nail	3.45	13	167	6' Rule, Zig-Zag	2.10	
104	11/16" Bit, Electrician	2.35	6	177	2 "Screw Driver	.45	
	12/16" Bit, Electrician	2.35 2.75	6	200 000	3 " Screw Driver	.45 .50	
	13/16" Bit, Electrician 14/16" Bit, Electrician	2.73	•	64 He A	4 "Screw Driver	.55	
	16/16" Bit, Electrician	3.20		10 4 may 4	8 " Screw Driver	.65	
106	6' Rule, Zig-Zag	1.75		180	12" Bit Extension	4.20	
106 106F	6' Rule, Zig-Zag	1.75		1 00.1	18" Bit Extension	4.40	
					24" Bit Extension	4.80	

No.	Item	Each	Page	No.	Item	Each	Page
101	Level, Camera	.90	18	289	Soldering Iron Tip	2.40	31
181 183	Level, Camera	.65	18	291B	2 oz. Hammer, Ball Pein	2.95	13
184	18" Bit Extension	2.60	8	292	Scraper	2.80	24
104	24" Bit Extension	2.80	8	C292	Scraper Iron	.40	24
185	4 1/2" Scraper Burnisher	1.45	24	293	Scraper	1.25	24
187	3¼" Level, Line	.85	17	294	10 " "Surform" Blade	.98	33
191	Soldering Iron Tip	2.00	31	295	16 % " "Surform"	2.69	33
192	Soldering Iron Tip	2.00	31	296	10 " "Surform"	3.69	33
193	Soldering Iron Tip	2.00		299	5½" Knife, Utility	1.00	16
199	6 "Knife, Utility	1.50	16	301	1 pt. Phillips Bits	.60	27
202	4/16" Bit, Car	2.60	6	301	Soldering Iron Tip	3.30	31
	5/16" Bit, Car	2.60 2.70	6	302	2 pt. Phillips Bits	.60	27
	6/16" Bit, Car	2.80	6	303	3 pt. Phillips Bits	.60	27
	8/16" Bit, Car	2.90	6	306	4 oz. Hammer, Ball Pein	2.95	13
	9/16" Bit, Car	3.10	6	306B	4 oz. Hammer, Ball Pein	2.35	
	10/16" Bit, Car	3.35	6	307	6 oz. Hammer, Ball Pein	2.95	
	11/16" Bit, Car	3.55 3.65	6	307B	6 oz. Hammer, Ball Pein	2.35	
	12/16" Bit, Car	3.75	6	308	8 oz. Hammer, Ball Pein	3.10 2.50	
	14/16" Bit, Car	4.10	6	308B	8 oz. Hammer, Ball Pein Chuck and Drill Set	2.25	00
	15/16" Bit, Car	4.30	6	309		3.20	
	16/16" Bit, Car	4.60	6	309	12 oz. Hammer, Ball Pein		4.0
210	2 ¾ " Chisel, Elec	3.25		309B	12 oz. Hammer, Ball Pein	2.60 3.45	40
2111/2	16 oz. Hammer, Nail	1.69		310 310B	16 oz. Hammer, Ball Pein 16 oz. Hammer, Ball Pein	2.85	40
211 16 A	16 oz. Hammer, Nail	1.69	4.0	B310W	10' Rule Blade	1.25	
213	7 oz. Hammer, Nail	1.64		The state of the s	20 oz. Hammer, Ball Pein	3.60	
215	%" Bit, Spade	1.05 1.10	77	311	1 pt. Phillips Bits	.60	
	½" Bit, Spade %" Bit, Spade	1.25	7	311	20 oz. Hammer, Ball Pein	3.10	
	% " Bit, Spade	1.30	7	311B	24 oz. Hammer, Ball Pein	3.80	
	%" Bit, Spade	1.35	7	312	2 pt. Phillips Bits	.60	0=
	1 " Bit, Spade	1.40		312	24 oz. Hammer, Ball Pein	3.25	
215A	Set, Spade Bit	7.80		312B	12' Rule Blade	1.50	
220	7 " Plane, Block	3.98		B312W		7.00	
221	32 oz. Hammer, Flooring	4.35	4 0	313	18" Level, Aluminum 24" Level, Aluminum	8.50	
221C	32 oz. Hammer, Flooring	5.15			28" Level, Aluminum	9.40	
X226	6' Rule, Zig-Zag	2.80		212	3 pt. Phillips Bits	.60	27
X227	6' Rule, Zig-Zag	2.50		313	32 oz. Hammer, Ball Pein	4.10	
230	4 oz. Hammer, Riveting 7 oz. Hammer, Riveting	3.35 3.35		314	4 pt. Phillips Bits	.65	
231 232	9 oz. Hammer, Riveting	3.60		314	32 oz. Hammer, Ball Pein	3.50	
233	12 oz. Hammer, Riveting	3.60		314B		3.55	
233	24" Level, Aluminum	9.95		315	4/16" Bit, Machine 5/16" Bit, Machine	3.55	_
	28" Level, Aluminum	10.95			6/16" Bit, Machine	3.55	7
244	Mitre Box	72.70		10 00 0	7/16" Bit, Machine	3.60	
246	Mitre Box	75.00			8/16" Bit, Machine	3.70	
250A	3/16" Wrench, Tap	4.40		F2 50	9/16" Bit, Machine	3.80 3.90	
251	16 oz. Hammer, Pros. Picks	4.50		14. 65	11/16" Bit, Machine	4.00	1
251A	5/16" Wrench, Tap	4.80		100	12/16" Bit, Machine	4.10	7
252	24 oz. Hammer, Pros. Picks	5.00			13/16" Bit, Machine	4.30	
255	24" Level, Magnesium	8.30		io jai	14/16" Bit, Machine	4.60	9.2
	28" Level, Magnesium 30" Level, Magnesium	9.50 10.00		L 18	15/16" Bit, Machine	4.90 <b>5</b> .20	
	48" Level, Magnesium	15.50		ALL MILE			
	72" Level, Magnesium	24.00		316	40 oz. Hammer, Ball Pein 40 oz. Hammer, Ball Pein	4.30 3.75	
	78" Level, Magnesium	26.00	17	316B	4/16" Bit, Machine	3.70	_
256	Soldering Iron Tip	2.00	31	317	5/16" Bit, Machine	3.70	
257	24" Level, Wood	4.40			6/16" Bit, Machine	3.70	
	28" Level, Wood	4.80			7/16" Bit, Machine	3.75	
260	9" Level, Torpedo	2.50		41 773	8/16" Bit, Machine	3.85	
261	1 pt. Phillips Screw Driver Bit	.85		. 80 0	9/16" Bit, Machine	3.95 4.05	
262	2 pt. Phillips Screw Driver Bit	.85		, 41.5	11/16" Bit, Machine	4.10	
263	3 pt. Phillips Screw Driver Bit	.85			12/16" Bit, Machine	4.20	, ,
263	9" Level, Torpedo	2.95		41. 01.0	13/16" Bit, Machine	4.45	4
264	9" Level, Torpedo	2.95		10 80.1	14/16" Bit, Machine	4.80	
266F	6' Rule, Zig-Zag	1.75		100 000	15/16" Bit, Machine	5.20 5.40	
271	3 " Plane, Router	2.50		100	16/16" Bit, Machine	6.20	11.5
					TO/ TO DIO MACHINE	30	
273 273 <b>A</b>	Soldering Iron Tip Soldering Iron Tip	2.00 2.10			20/16" Bit, Machine	6.80	) '

No.	Item	Each	Page	No.	Item	Each	Page
319	Chuck and Drill Set	2.25	28	595	16 oz. Hammer, Soft Face	3.00	16
320	Soldering Iron	11.00	30	595A	Hammer Tip	.55	16
320T	Soldering Iron Tip	1.00	30	601	5 oz. Hammer, Magnetic Tack	3.25	15
330	Soldering Iron	11.50	30	602	7 oz. Hammer, Upholsterers'	3.80	15
330T 340	Soldering Iron Tip Soldering Iron	1.10 12.20	30 30	605	1 oz. Hammer, Tack Claw	.65	15
340T	Soldering Iron Tip	1.20	30	610	¼" Drill, Hand	7.70	11
345T	Soldering Iron Tip	.90	31	611	% " Drill, Hand	8.60	11
346	Mitre Box	78.00	18	624	%" Drill, Hand	9.95	11
348W	8' Rule, "Pull-Push"	1.98	21	668 669	3" Offset Screw Driver 4" Offset Screw Driver	.45 .45	28 28
350	Soldering Iron	13.50	30	670	5" Offset Screw Driver	.50	28
350T	Soldering Iron Tip	2.40	30	670H	3 lbs. Hammer, Masons'	6.11	15
351X	1 pt. Phillips Bits	.60	27	0.011	4 lbs. Hammer, Masons'	6.57	15
352X	2 pt. Phillips Bits	.60	27	671	6" Offset Screw Driver	.60	28
355T	Soldering Iron Tip	1.20	31	700	31/2" Vise, Wood Workers'	7.50	33
358	Mitre Box	81.00	18	702	3½" Vise, Wood Workers'	4.75	33
359	Chuck and Drill Set	1.20	28	750	1/8" Chisel, Wood	2.10	9
360	Mitre Box	87.00	18	10.6	" Chisel, Wood	2.00	9
360	Soldering Iron	14.70	30	3.71	% " Chisel, Wood	2.10	9
360T	Soldering Iron Tip	2.80	30	7 5 91.5	½" Chisel, Wood	2.20	9 9
361	Soldering Iron Tip	2.20	31	- BCA	% " Chisel, Wood	2.20 2.30	9
364	9" Level, Torpedo	4.30	17		% " Chisel, Wood	2.40	9
365T	Soldering Iron Tip	2.20	31	10 K 10 K	1 " Chisel, Wood	2.40	9
370	Soldering Iron	17.80	30		1¼" Chisel, Wood	2.90	9
370T	Soldering Iron Tip	4.70	30		1½" Chisel, Wood	3.20	9
373	3 "Butt Marker	1.60	9		2 " Chisel, Wood	3.90	
373 1/2	3½" Butt Marker	1.60	9	750H	4 lbs. Hammer, Striking 6 lbs. Hammer, Striking	5.47 7.91	15 15
374	4 " Butt Marker	1.60	9		8 lbs. Hammer, Striking	8.48	15
380	Soldering Iron	19.50	30	1.0	10 lbs. Hammer, Striking	9.90	15
380T	Soldering Iron Tip	5.50	30		12 lbs. Hammer, Striking	10.96	15
382	32 oz. Hammer, Engineers'	4.80	14		16 lbs. Hammer, Striking	13.91	15
383	40 oz. Hammer, Engineers'	5.10	14	760H	4 lbs. Sledge, Handled	5.47	16
384	48 oz. Hammer, Engineers'	5.35	14	926 2011	6 lbs. Sledge, Handled	7.91	16
385T	Soldering Iron Tip	2.90	31	H - 41 -	8 lbs. Sledge, Handled	8.48	16 16
390	Soldering Iron	21.60	30	010 24.5	10 lbs. Sledge, Handled 12 lbs. Sledge, Handled	9.90 10.96	16
392	40 oz. Hammer, Engineers'	5.10	14	701			33
393	48 oz. Hammer, Engineers'	5.35	14	761 763	1½" Vise	9.30 9.90	33
400	Mitre Vise	24.00	19	765	2½" Vise	11.85	33
401	32 oz. Hammer, Blacksmiths'	4.80	14	766	3 " Vise	13.90	33
402 403	40 oz. Hammer, Blacksmiths' 48 oz. Hammer, Blacksmiths'	5.10 5.35	14 14	780H	2 lbs. Hammer, Hand Drilling	4.20	15
				1100000	3 lbs. Hammer, Hand Drilling	4.40	15
404	Mitre Clamp	2.25	19	(4.1.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4.4	4 lbs. Hammer, Hand Drilling	4.80	15
B410W B412W	10' Rule Blade	.85 1.00	$\begin{array}{c} 21 \\ 21 \end{array}$	813	10" Bit Brace	12.90	7
	2 " Screw Driver		26	90.87	12" Bit Brace	13.40	7
415	3 " Screw Driver	.50 .60	26	816	6' Rule, Zig-Zag	1.80	23
	4 " Screw Driver	.70	26	818	34" Chisel, Rip	2.49	10
	6 "Screw Driver	.85	26	830H	6 lbs. Sledge, Cross Pein	8.26	16
	8 " Screw Driver	.90	26	00011	8 lbs. Sledge, Cross Pein	8.93	16
417	10 " Screw Driver	1.00 .90	$\begin{array}{c} 26 \\ 26 \end{array}$		10 lbs. Sledge, Cross Pein	10.28	16
417	6 " Screw Driver	.95	26		12 lbs. Sledge, Cross Pein	11.67	16
430A	10 oz. Hammer, Bricklayers'	3.70	15		16 lbs. Sledge, Cross Pein	14.64	16
431A	18 oz. Hammer, Bricklayers'	3.95	15	84 <b>0H</b>	8 lbs. Sledge, Straight Pein	8.93	16
431 16 A	24 oz. Hammer, Bricklayers'	4.25	15	11 11 11	12 lbs. Sledge, Straight Pein	11.67	16
432A	32 oz. Hammer, Bricklayers'	4.70	15	J. Long St. Co.	14 lbs. Sledge, Straight Pein	13.13	16
451	8 oz. Hammer, Tinners'	3.60	15	850H	40 oz. Hammer, Engineers'	3.60	14
452	12 oz. Hammer, Tinners'	3.60	15	225 101.5	48 oz. Hammer, Engineers' 64 oz. Hammer, Engineers'	4.10	14
453	16 oz. Hammer, Tinners'	3.75	15	0.5011		4.60	14
461 462	8 oz. Hammer, Tinners' 12 oz. Hammer, Tinners'	3.60 3.60	15 15	850H	4 lbs. Sledge, Double Face 6 lbs. Sledge, Double Face	4.60 7.91	16 16
463	16 oz. Hammer, Tinners'	3.75	15	15 50	8 lbs. Sledge, Double Face	8.48	16
464	20 oz. Hammer, Tinners'	3.90	15	100	10 lbs. Sledge, Double Face	9.90	16
510	5-10' Extension St	11.70	23	11 64 5	12 lbs. Sledge, Double Face	10.96	16
592	1½ oz. Hammer, Soft Face	1.60	16		16 lbs. Sledge, Double Face	13.91	16
592A	Hammer Tip	.30	16	100 100.31	20 lbs. Sledge, Double Face	16.92	16
593	4 oz. Hammer, Soft Face	2.00	16	860H	32 oz. Hammer, Engineers'	3.70	14
593A	Hammer Tip	.35	16	21 00 0	40 oz. Hammer, Engineers'	3.80	14
594	8 oz. Hammer, Soft Face	2.50	16 16		48 oz. Hammer, Engineers' 64 oz. Hammer, Engineers'	4.10	14
594A	Hammer Tip	.48		18 00.8		4.60	

No.	Item	Each	Page	No.	Item	Each	Page
861H	32 oz. Hammer, Engineers'	3.70	14	H1270	3 " Screw Driver	.29	25
0.8	40 oz. Hammer, Engineers'	3.80	14	32 02.0	4 "Screw Driver	.35	
	48 oz. Hammer, Engineers'	4.10	14	U 09 A	5 "Screw Driver	.39	
	64 oz. Hammer, Engineers'	4.60	14	31 2011	6 "Screw Driver	.39	
901	1 pt. Phillips Screw Driver	.95	26	1070	8 "Screw Driver	.59	25
902	2 pt. Phillips Screw Driver	1.00	26	1272	2 " Screw Driver	.45 .45	
903	3 pt. Phillips Screw Driver	1.20	26	E1 2 7	4 " Screw Driver	.52	
904	4 pt. Phillips Screw Driver	1.50	26	82 Or 7	5 " Screw Driver	.58	25
923	8" Bit Brace	11.95	7	E 01 1	6 " Screw Driver	.65	25
	10" Bit Brace	11.95 12.40	77	68 68.4	8 "Screw Driver	.85	25
02011			16	M1 99 1	10 "Screw Driver	1.00	25
930H	4 lbs. Maul, Ship	8.42 9.66	16	B 27-	12 " Screw Driver	1.15	25
045	5 lbs. Maul, Ship			1442	Bull Point	2.65	9
945	10" Bit Brace	7.50	8	1443	Bull Point	3.00	9
960H	6 lbs. Maul, Wood Choppers'	8.57	16	1444	Bull Point	3.10	9
	8 lbs. Maul, Wood Choppers'	9.90	16	1445	Bull Point	3.50	9
965N	10" Bit Brace	5.30	8	1446 1447	Bull Point	4.35 5.20	9
975	3 lb. Wedge, Square Head	2.04	35	1448	Bull Point	5.70	9
	4 lb. Wedge, Square Head	2.26	35	1449	Bull Point	6.10	9
	5 lb. Wedge, Square Head	2.41	35	1450	3 " Chisel, Brick	1.70	9
	6 lb. Wedge, Square Head	2.84	35 35	1430	3½" Chisel, Brick	1.80	9
	8 lb. Wedge, Square Head	3.70			4 " Chisel, Brick	2.05	9
980X	4 lb. Wedge, Splitting	2.53	35 35	1451	3" Screw Driver—Cross-point.	.70	26
	5 lb. Wedge, Splitting 6 lb. Wedge, Splitting	2.70 3.10	35	1452	4" Screw Driver—Cross-point.	1.00	26
	8 lb. Wedge, Splitting	3.92	35				
004	7" Bit Brace, Corner	14.40	8	1460 1470	% Chisel, Rip	2.59 2.80	10 10
984							
990	3 "Vise, Utility	11.20	34	1523	%" Plug Cutter	3.50	30
991	1½" Vise, Mechanics'	9.84	34	11 190	½" Plug Cutter	4.25	30
992	118 " Vise, Mechanics'	10.80	34		%" Plug Cutter	4.25	30
993	3 "Vise, Mechanics'	16.60	$\frac{34}{34}$	1524	1 "x # 8 Counterbore	1.25	29
994		34.80		100 0.1	1 " x #10 Counterbore	1.25	29
1006	3 " Screw Driver	1.25	26 26	40 mm	1¼" x # 8 Counterbore	1.25	29
	4 " Screw Driver	1.25 1.60	26	549 mm	1¼" x #10 Counterbore 1½" x #10 Counterbore	1.25	29 29
	8 " Screw Driver	1.95	26		1½" x #12 Counterbore	1.25 1.25	29
	10 " Screw Driver	2.10	26		1%" x #10 Counterbore	1.25	29
	12 " Screw Driver	2.80	26	-	1% " x #12 Counterbore	1.25	29
1007	4 " Screw Driver	1.40	26		2 " x #14 Counterbore	1.25	29
	6 "Screw Driver	1.80	26	- 12	2 " x #18 Counterbore	1.25	29
	8 " Screw Driver	2.25	26	1525	1/2" x # 5 Screw-Mate Tool	.75	29
	10 "Screw Driver	2.70	26	1020	%4" x # 6 Screw-Mate Tool	.75	29
1000	12 Sciew Dilver	2.95	26	100	% " x # 7 Screw-Mate Tool	.75	29
1008	3 " Screw Driver	1.00	$\begin{array}{c} 26 \\ 26 \end{array}$		34" x # 8 Screw-Mate Tool	.75	29
	8 " Screw Driver	1.10	26	1.1	1 "x # 6 Screw-Mate Tool	.75	29
	10 " Screw Driver	1.25	26		1 "x # 7 Screw-Mate Tool	.75	29
1009	1 % " Screw Driver	.80	26		1 "x # 8 Screw-Mate Tool 1 "x #10 Screw-Mate Tool	.75	29
1010	2 " Screw Driver	.35	26		1 14" x # 8 Screw-Mate Tool	.75	29
1012	1 " Screw Driver	.70	26	120	14 x # 8 Screw-Mate Tool	.75 .75	29 29
1013	1 "Screw Driver	.50	26	1 1	14" x #10 Screw-Mate Tool	.75	29
1016	3 " Screw Driver	.50	26	11 100	1 4 " x #12 Screw-Mate Tool	.75	29
1017	Instrument Screw Driver	.20	29	82 07.1	1 4 " x #14 Screw-Mate Tool	.75	29
1070H	16 oz. Hammer, Scaling	2.85	14	42 07.1	1½" x # 8 Screw-Mate Tool	.75	29
1206W	6' Rule, "Pull-Push"	1.10	22	ATT THE	1½" x #10 Screw-Mate Tool	.75	29
1208	8' Rule, "Pull-Push"	1.35	22	198 day L	1 1/2" x #12 Screw-Mate Tool	.75	29
1208W	8' Rule, "Pull-Push"	1.35	22	18.	1½" x #14 Screw-Mate Tool	.75	29
1210	10' Rule, "Pull-Push"	1.65	22	78 00.	1 % " x # 8 Screw-Mate Tool	.75	29
1210W	10' Rule, "Pull-Push"	1.65	22	70 90	1 % " x #10 Screw-Mate Tool 1 % " x #12 Screw-Mate Tool	.75	29
1212W		1.98	22	F 401	2 " x #12 Screw-Mate Tool	.75 .75	29 29
H1227	4/16" Bit, Auger	1.00	6	11 07	2 "x #12 Screw Mate Tool	.75	29
	5/16" Bit, Auger	1.00	6	87 07	2 " x #14 Screw-Mate Tool	1.25	29
	6/16" Bit, Auger	1.00 1.05	6	48 67.	2½" x #12 Screw-Mate Tool	1.25	29
	8/16" Bit, Auger	1.08	6	1530A	9 mill, Hand	13.20	11
	9/16" Bit, Auger	1.12	6	1721	1 pt. Phillips Screw Driver	.55	27
	10/16" Bit, Auger	1.15	6	1721	2 pt. Phillips Screw Driver	.69	27
	11/16" Bit, Auger	1.22	6	1723	3 pt. Phillips Screw Driver	.85	27
	12/16" Bit, Auger	1.25	6	1991	Knife Blades	.50	16
	13/16" Bit, Auger	1.35	6				_
	14/16" Bit, Auger	1.40	6	1991	1½" Vise, Mechanics'	13.74	34
	15/16" Bit, Auger	1.50	6	1991C	Knife Blades	7.00	16
	16/16" Bit, Auger	1.55	6	1992	Knife Blades	.60	16
1251A	5/16" Wrench, Tap	7.00	33	1992	118 " Vise, Mechanics'		34

No.	Item	Each	Page	No.	Item	Each	Pag
1992C	Knife Blades	8.00	16	3201	Soldering Iron	11.00	30
1993	3 "Vise, Mechanics'	23.20	34	3301	Soldering Iron	11.50	30
1994	4 " Vise, Mechanics'	48.20	34	3400	Offset Ratchet	1.00	28
995	Knife Blades	1.25		3401	Soldering Iron	12.20	30
006	3 " Screw Driver	.85		3410W	10' Rule, "Pull-Push"	2.39	~
Real Real	4 " Screw Driver	.90	~ =	3412	Offset Ratchet	1.75	
	6 " Screw Driver	1.25 1.70	~ =	3412W	12' Rule, "Pull-Push"	2.89	2
932 55-	. " a D '	1.10	~~	3423	Offset Ratchet	1.75	-
2007	4 " Screw Driver	1.50	~~	3510	Set Sp. Ratchet Bits	1.50	2 2
	8 " Screw Driver	1.85	25	3511	5/32" Sp. Ratchet Bits	.50 .50	
2008	3 " Screw Driver	.70		3512 3513	3/32" Sp. Ratchet Bits	.50	-
4 47-5	6 " Screw Driver	.80 .95		3530	Countersink	.50	2
	8 "Screw Driver		-	3541	Spiral Drill Bit, Heavy Duty	.70	2
101	8" Bit Brace	16.40 16.40	_	3551	Spiral Drill Bit with Sleeve	1.70	2
	10" Bit Brace	16.70		3580	Chuck Adapter	.40	2
	14" Bit Brace	17.40	_	3600	Ratchet Handle Screw Driver	1.20	2
136	36" Bar, Ripping	3.90	5	3600-9	Ratchet Kit	5.10	2
150	15" Bit Extension	5.60	8	3601	1/4 " Adapter, Screw Driver.	.40	2
.130	18" Bit Extension	5.60		3602	13/32" Adapter, Screw Driver.	.40	2
	21" Bit Extension	5.90	•	3610W	10' Rule, "Pull-Push"	2.49	2
	24" Bit Extension	6.20	70.	3611	5/64" Adapter, Hex Key	.40	2
244	Mitre Box	76.00 78.00		3612	3/32" Adapter, Hex Key	.40	2
246	Mitre Box	85.00	40	3612W	12' Rule, "Pull-Push"	2.98	2
358 360	Mitre Box	28.90	10	3613	1/8 " Adapter, Hex Key	.40	
	1 pt. Phillips Screw Driver	.75	26	3614	5/32" Adapter, Hex Key	.40	-
501 502	2 pt. Phillips Screw Driver	.80	00	3615	3/16" Adapter, Hex Key	.40	
513	48" Level, Wood	17.00	17	3616	7/32" Adapter, Hex Key 1/4 " Adapter, Hex Key	.40 .40	-
701	1 pt. Phillips Screw Driver	.50	26	3617	5/16" Adapter, Hex Key	.40	
702	2 pt. Phillips Screw Driver	.60		3618	1 pt. Adapter, Phillips Bit	.65	_
703	3 pt. Phillips Screw Driver	.75		3631 3632	2 pt. Adapter, Phillips Bit	.65	2
704	4 pt. Phillips Screw Driver	1.00 .55		3633	3 pt. Adapter. Phillips Bit	.65	
711	1 pt. Phillips Screw Driver 2 pt. Phillips Screw Driver	.60		3634	4 pt. Adapter, Phillips Bit	.65	
712 750	0 pt. Phillips Screw Driver	.50	27	3800	Offset Ratchet	1.75	
751	1 pt. Phillips Screw Driver	.70		3992	118 " Vise, Angle	16.70	
752	2 pt. Phillips Screw Driver	1.00 1.35		3993	3 1/8" Vise, Angle	23.70	
753	3 pt. Phillips Screw Driver 4 pt. Phillips Screw Driver	1.90	~~	4992	118 " Vise, Angle	23.20 30.00	
754	2 pt. Phillips Screw Driver	.95		4993	3 1/8" Vise, Angle	2.30	
762	Vise Clamp	4.85		5930	6 oz. Hammer, Soft Face Hammer Tip	.42	_
992 993	Vise Clamp	6.18	34	5930A 5950	32 oz. Hammer, Soft Face	7.70	15
010	Set Sp. Ratchet Bits	1.50		5950A	Hammer Tip	.85	
011	7/32" Sp. Ratchet Bits	.50	0=	5991	Swivel Base	4.50	
012	1/4 "Sp. Ratchet Bits	.50 .50		5992	Swivel Base	5.94	
013	9/32" Sp. Ratchet Bits	.70		5993	Swivel Base	6.60 13.40	
030	Countersink	.70		5994	5 oz. Hammer, Magnetic Tack	3.90	
041 042	Spiral Drill Bit, Heavy Duty	.70	28	6010	7 oz. Hammer, Upholsterers'	4.50	
043	Spiral Drill Bit, Heavy Duty	.70		6020		4.29	
051	Spiral Drill Bit with Sleeve	1.70		6325	25' Tape, Steel	5.29	
053	Spiral Drill Bit with Sleeve	1.70		6350 6375	75' Tape, Steel	6.29	
080	Chuck Adapter	.40		6992	Swivel Base	5.94	
110	Set Sp. Ratchet Bits	1.50 .50	~-	6993	Swivel Base	6.60	) ;
111	1/4 " Sp. Ratchet Bits 9/32" Sp. Ratchet Bits	.50	0=	7991	"V" Block	.80	
112	5/16" Sp. Ratchet Bits	.50	~=	7992	"V" Block	1.10	
3113	Countersink	.70		7993	"V" Block	2.00	
3130	Spiral Drill Bit, Heavy Duty	.70		7994	"V" Block	2.80	
3141	Spiral Drill Bit. Heavy Duty	.70	28	8030	Tool Holder Bit	.40 .40	
3142 3143	Spiral Drill Bit, Heavy Duty	.70		8035	Tool Holder Bit	7.29	
3152	Spiral Drill Bit with Sleeve	1.70		63100	100' Tape, Steel	.90	
3153	Spiral Drill Bit with Sleeve			Type G	Jaws	1.10	
3180	Chuck Adapter			Type I	Jaws	1.	10

